Operator: CRAWFORD COUNTY GAS GATHERING, LLC Operator ID#: 32	
Inspection Date(s): 12/5/2013 (Half)	Man Days: 0.5
Inspection Unit: Crawford County Gas, LLC	
Location of Audit: Lawrenceville	
Exit Meeting Contact:	
Inspection Type: Standard Inspection - Field Audit	
Pipeline Safety Representative(s): Charles Gribbins,	
Company Representative to Receive Report: Don Jones	
Company Representative's Email Address: donjones@pioneeroil.net	

Headquarters Address Information:	R. R. 4	
	Box 142B	
	Lawrenceville, IL 62439	
	Emergency Phone#:	
	Fax#:	
Official or Mayor's Name:	Don Jones	
	Phone#: (618) 943-5314	
	Email: donjones@pioneeroil.net	
Inspection Contact(s)	Title	Phone No.

	CUSTOMER METER & REGULATOR	Status
Category Comment:		
This is a transmission line	e no services attached.	
[192.353(a)]	Is the customer meter and regulator installed in a readily accessible location and protected from corrosion and other damage, including if installed outside a building, vehicular damage that may be anticipated?	Not Applicable
[192.355(b)(1)]	Is the customer regulator vent rain and insect resistant?	Not Applicable
[192.355(b)(2)]	Is the customer regulator vent located where gas from the vent escapes freely into the atmosphere and away from building openings?	Not Applicable
[192.355(b)(3)]	Is the vent protected from damage caused by submergence in areas of flooding?	Not Applicable
[192.357(a)]	Is the customer meter and regulator installed to minimize anticipated stresses	Not Applicable

	upon connecting piping?	
[192.357(d)]	Is a customer regulator that might release gas vented to the outside atmosphere?	Not Applicable
[192.359(a)]	Is the meter operating pressure within the allowable limits of the meter case rating?	Not Applicable
[192.365(a)]	Is the service line valve upstream of the regulator or meter?	Not Applicable
[192.365(c)]	Is the underground service line valve located in a curb box or standpipe that allows for ready operation?	Not Applicable
[192.727(d)][192.727(d)]	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?	Not Applicable
	CATHODIC PROTECTION	Status
[192.463(a)]	Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?	Satisfactory
[192.465(a)]	Were pipe to soil readings taken?	Satisfactory
South section of main 1.050 vo All reading were well above the [192.465(b)]		Not Applicable
	, ·	
General Comment:	Were reduier installations inspected.	Not Applicable
There are no rectifiers on the to	ransmission line.	
[192.465(a)]	Were isolated mains/services tested?	Not Applicable
General Comment:		
There is no isolated main secti	ons.	
[192.465(c)]	Were critical/non critical bonds tested?	Not Applicable
General Comment:		
There are no critical/non-critical	al bonds on the system.	
[192.467(a)]	Is electrical isolation provided by use of insulated meter spud, valve, union, or flange?	Satisfactory
General Comment:		
Electrical isolation is provided i	by use of insulated flanges.	
[192.467(c)]	Were casings installations tested for electrical isolation?	Not Applicable
General Comment:	1	• • •

There are no casings on	the pipeline.	
[192.479(a)]	Is the above ground piping coated or painted as required?	Satisfactory
[192.479(c)]	Is the pipeline free of corrosion or pitting?	Satisfactory
	DAMAGE PREVENTION	Status
[192.614]	Does the operator have a valid notification of planned excavation activities?	Not Applicable
General Comment:		
There were no planned e	excavation activities at the time of inspection.	
[265.40(a)]	Did the operator complete the locating activities in the specified timeframe?	Not Applicable
General Comment:		
There were no planned e	excavation activities at the time of inspection.	
[192.614(c)(5)]	Were temporary markings made in accordance with the operator's Operation and Maintenance Manual?	Not Applicable
General Comment:  There were no planned e	excavation activities at the time of inspection.	
[192.707(a)(1)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located at each crossing of a public road and railroad?	Satisfactory
General Comment:		
Line markers were inspe	cted along the 1400 of pipeline.	
[192.707(a)(2)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located wherever necessary to identify the location of the transmission line or main to reduce the possibility of damage or interference?	Satisfactory
[192.707(c)]	Are line markers placed and maintained as close as practical over each main and transmission line located above ground?	Satisfactory
[192.707(d)(1)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The word "Warning," "Caution," or "Danger" followed by the words "Gas (or name of gas transported) Pipeline" all of which, except for markers in heavily developed urban areas, must be in letters at least 1 inch (25 millimeters) high with ¼ inch (6.4 millimeters) stroke?	Satisfactory
General Comment:		
The line markers contain	ed the correct information as required by 192.707.	
[192.707(d)(2)]	Do the operator's line markers contain the following information: The following	Satisfactory

The operator is not required to	odorize the natural gas.	
Category Comment:	ODORIZATION OF GAS	Status
This for a distribution valve req		_
General Comment:		
[192.747(a)]	Were the valves inspected accessible?	Not Applicable
	VALVE MAINTENANCE	Status
[192.199(h)]	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?	Satisfactory
[192.199(e)]	Did the pressure relief or pressure limiting devices inspected to determine if the discharge stacks, vents, or outlet ports were designed to prevent accumulation of water, ice, or snow, and located where gas can be discharged into the atmosphere without undue hazard?	Satisfactory
[192.199(d)]	Did the pressure relief or pressure limiting devices inspected to determine if the support was made of noncombustible material?	Satisfactory
General Comment:  The pipeline is at or above the	MAOP of the transmission company.	
[192.743(a)]	Is overpressure protection provided on the pipeline down stream of the take point?	Not Applicable
The operator monitors the pres	ssure by electronic means.	
General Comment:		
[192.741(a),192.741(c)]	Were telemetering and/or recording gauges inspected for abnormally high or low pressure indications?	Not Applicable
[192.317(b)]	Is each above ground transmission line or main protected from accidental damage by vehicular traffic or other similar causes?	Satisfactory
There is pressure control and o	overpressure devices but not a pressure regulating station.	
General Comment:	other conditions that might prevent proper operation.?	
[192.739(a)(4)]	Was each pressure limiting station, relief device (except rupture discs), and pressure regulating station and its equipment subjected at intervals not exceeding 15 months, but at least once each calendar year, to inspections and tests to determine that it is properly installed and protected from dirt, liquids, or	Satisfactory
PRESSURE	LIMITING AND REGULATING DEVICES (MECHANICAL)	Status
	marker: The name and phone number (including area code) of the operator where the operator can be reached at all times?	

[192.625(a)]	Was the odor intensity level readily detectable at or below 1/5th LEL?	Not Applicable
[192.625(e)]	Was the Odorization equipment and tank levels inspected?	Not Applicable
[192.625(f)]	Was the operator's equipment calibrated as required?	Not Applicable
	TRANSMISSION	Status
[192.179(b)(1)]	Are transmission valves protected from tampering or damage?	Satisfactory
[192.745(a)]	Were the valves inspected accessible?	Satisfactory
[192.719(a)]	Is pre-tested transmission pipe inventory maintained for use in an emergency?	Not Checked
General Comment:		
Staff did inspect pipe inv	entory.	
	MARKING OF MATERIAL	Status
[192.63(a)]	Does the operator's components and pipe contain the required markings?	Not Checked
General Comment:	•	
Staff did not inspect pipe	inventory.	
	OPERATOR QUALIFICATION	Status
Category Comment:		
Staff did not conduct a fi	eld inspection on operator qualification	